York Farm

Chestertown

No expense was spared in the construction of York House. The elaborate brackets; applique work; and interior and exterior trim are the best and most costly that 19th century catalogues had to offer. Located on the northwest side of Quaker Neck Road near the Route 661 junction, this frame house is 2-1/2 stories and cross-shaped in plan with generous one-story porches filling in at three corners of the cross. The house's floor plan is unusual for Kent County and is clearly an attempt to sensibly accommodate a large number of rooms while keeping the house well balanced visually. A group of 19th century farm buildings are clustered behind the house. York Farm, one of Kent County's most picturesque and largest Victorian country homes, is a showcase of late 19th century architectural ornament.

Survey No. K-459

Maryland Historical Trust State Historic Sites Inventory Form

Magi No.1504595635

4 1				
1. Nam	e (indicate pr	eferred name)		
historic York	Farm			
and/or common	Eliason Far	m		
2. Loca				
street & number		Quaker Neck Road, Mit t Route 661 turn off		not for publication
city, town	Chestertown	X vicinity of	congressional district	FIRST
state	Maryland	county	Kent	
3. Clas	sification			
Category district _X building(s) structure site object	Ownership public private both Public Acquisition in process being considered not applicable	Status _X_ occupied unoccupied work in progress Accessible yes: restricted yes: unrestricted _X_ no	Present Use agriculture commercial educational entertainment government industrial military	museum park X private residence religious scientific transportation other:
4. Own	er of Prope	rty (give names ar	nd mailing addresse	es of <u>all</u> owners)
name Thom	as Walker Eliason Byford Hei	ghts	telephone n	301-778-0597
city, town	Chestertown	state	and zip codeMaryl	land, 21620
5. Loca	ation of Leg	al Description	on	
courthouse, regi	stry of deeds, etc. Ken	t County Court Ho	use	liber EHP53
street & number				folio 7
city, town	Chestertown		state	Maryland
6. Rep	resentation	in Existing	Historical Surv	veys
title				
date			federal sta	ite county local
uepository for su	urvey records			
city, town	-		state	
*		-		

7. Des	cription		Survey No. K-459		
Condition excellent good fair	deteriorated ruins unexposed	Check one unaltered altered	Check one original site moved date of move		

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

Built between 1883 and 1893, this frame house is $2\frac{1}{2}$ stories tall and cross-shaped in plan with generous one-story porches filling in three corners of the cross. No expense was spared in the construction of the house and elaborate brackets, applique work, and interior and exterior trim are the best and most costly that 19th century catalogues had to offer.

Period prehi 1400 1500 1600 1700 1800 1900-	-1499 archeology-historic -1599 agriculture -1699 _X architecture -1799 art -1899 commerce		politics/government	e religion science sculpture social/ humanitarian theater transportation X other (specify)
Specific	dates	Builder/Architect		
check:	Applicable Criteria:A and/or Applicable Exception:		E F G	
	Level of Significance:		local	
Prepare	both a summary paragraph	of significance and a	a general statement	of history and

Survey No. K-459

8. Significance

Prepare both a summary paragraph of significance and a general statement of history and support.

One of Kent County's most picturesque and largest Victorian country houses, York Farm is a show case of late 19th century architectural ornament. Eleborate brackets, stair parts, doors and other details were used here with enthusiasm, and a good sense of proportion. The house's floor plan is unusual for Kent County and is clearly an attempt to sensibly accommodate a large number of rooms while keeping the house well-balanced visually. Another interesting aspect of York Farm is the group of 19th century farm buildings clustered behind the house.

9. Major Bibliographical References

10. Ge	ographical Data		
Quadrangle name	nated propertye do NOT complete UTM refe		Quadrangle scale
A Zone Eastir		B Zone	Easting Northing
C		D	
	ry description and justification	rlanning state or co	unty houndaries
state	code	county	code
state	code	county	code
11. For	m Prepared By		
organization	Marsha L. Fritz, Surveyo County Commissioners of Historical Society of Ke	Kent County	7 - 7
street & number	The Court House Church Alley	tel	778-4600 lephone 778-3499
city or town	Chestertown	sta	ate Maryland 21620

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Maryland Historical Trust

Shaw House

21 State Circle

Annapolis, Maryland 21401

(301) 269-2438

7.1 DESCRIPTION (continued)

Building Form and Material

- 1. Size Main Section: $2\frac{1}{2}$ stories, 8 bays wide, 4 bays deep.
- 2. Plan type Cross-plan, no wings. See sketch plan.
- 3. Roof type Steep gable with dormers
- 4. Chimneys Location: 1) 2-flue chimney at crossing of cross; 2) enclosed in east gable (kitchen); 3) between stair hall and west rooms (#2 & 3 single flue) Materials: Brick; # 1 & #2 recently rebuilt of modern brick. Decorative elements: #1 & #2 - double band. #3, the only original, has banding plus outset brick detail on all four faces.
- 5. Material/Walls Frame: Lapped weatherboarding about 5" appears to be cypress
- 6. Material/Roofs Main Section: Green/black blend asphalt shingle
 Porch A: Asphalt roll roofing
 Porch B: Standing seam
 Porch C: Asphalt roll roofing
- 7. Material/Foundation Main Section: Common bond brick
 Porch A: Same
 Porch B: Same
 Porch C: Brick Piers
- 8. Age 1883-1893
- 9. Style Vernacular Victorian

Building Elements and Details

1. Doors - Main entry: Into stairhall. The third bay from the west, on the south facade. Originally the main entry was probably through porch B, where the grandest entry door is located. The present door is small and low, an incongruous element. - Entry door front exterior: The doorway has plain trim (4") and plain sill. There is a bold hood with decorative brackets & cyma recta and fillet crown mold. The door has an upper light with applique work below the sash and a top molding. Entry door from Porch B: Double doors with detail similar to above but with single-light transom and 2-light side lights. The glasses are cut and etched with a beautiful geometric pattern and no upper lights but a shallow "pedimented" hood molding above the upper panel. Above this door is a bold hood about 10" deep.

7.2 DESCRIPTION (continued)

Entry door to Kitchen: simple, 4-panel with glass added to upper panels.

Rear door to stair hall: 4-panel with rounded upper panels edged with bolection moldings.

- 2. Windows Type: Double hung Lights: 2/2 except 1/1 in bay Details: Very slender muntins in windows. Plain wooden trim and sills. About 3" hood molding of a double fillet and cove on the east section and a double fillet and cyma reversa (probably) elsewhere. Shutters: Wooden louvered with operable lower panel. Front Bay Window: Octagonal with a pair of narrow 1/1 sash windows in front and one window in each angled side. Beneath each window is a pyramidal panel. The angled corners are finished with a recessed quirked bead. The roof is hipped, covered with flat soldered metal roofing, and has cornice details which duplicate the main-house roof but in miniature.
- 3. Dormers Gable with overhanging eaves, 2/2 sash, horizontal weatherboarding on the cheeks. The eaves are boxed and have composite crown moldings. On the front (south) dormers there is applique in the tympanum and small brackets at the top and base of the pilasters.
- 4. Roof Details The same cornice details are used throughout the west and front pavillion of the cross gable. This is a box cornice overhanging about 14" with a cyma recta and fillet crown-molding. There is a circa 3' return at all gables. Elaborate wood brackets are spaced about 14" on center and there is a corner drop/foliated base. The fascia at the top of the wall is deep and finished with a molding (probably a Greek ogee and bevel). An additional molding about 5" from the bottom of this fascia adds an additional horizontal shadow line. The cornice on the east section of the house is the same but with a fillet and bevel bed molding instead of brackets.
- 5. Porches Porch A has square chamfered posts and a flat roof with cyma recta and fillet crown-molding. Porch B has a shallow shed roof with shallow box cornice. It probably had brackets; a foliated wooden "ginger bread" scallop on the underside of the beam remains behind screening. A portion of this porch is enclosed as a main entry. Porch C is one bay with a turned post flat roof.
- 6. Color Current: white/green shutters Historic: ?

- 7.3 DESCRIPTION (continued)
- 7. Other The lower edge of the weather-boarding is finished with a 6" board surmounted by a bold, beveled drip cap. There are 5" cornerboards.

Interior Description

- 1. Plan type see sketch plan
- Major stair Dogleg, open to third floor. Large Walnut newel with cable molding applied to octagonal shaft. Balusters, turned with acanthus leaf carving on lower portion. Open string with step brackets. See illustrations.
 Other Stairs Enclosed leading to kitchen. See floor plan sketch.
- 3. Major mantles In south and west rooms, first floor marbelized slate with round fireplace opening. North room, first floor simple slate mantle with rectangular opening and shelf supported by cast iron brackets. Second floor wooden mantles with reeding on frieze and pilasters.
- 4. Major trim Windows/doors: In major rooms wide reeded trim.
 On second floor and secondary first floor rooms wide trim with
 inside bead and wide fillet-ogee-fillet-bead backband.
 Baseboards: Circa 6" with ogee upper molding
- 5. Major doors 4-panel with applied Grecian ogee and bevel panel molding.
- Floors Medium width random yellow pine with narrow oak in major rooms.
- 7. Walls/ceiling finished Plaster, wallpaper, some modern plywood paneling.

Outbuildings/Site Description

Major outbuildings:

Smokehouse: one story gable roofed - vertical boarding on exterior, sheet metal roof, about 14' square. bay framing - 19th century.

Small barn/storage: 1½ story, gable roofed. rough, wide weatherboarding, brick foundation, metal roof. frame - bay framed.

Corn crib: long and narrow/shell on shed room. frame set on piers. stud with wooden cribbing.

7.4 DESCRIPTION (continued)

Cow barn/with silo and additions: 2 story/hay loft, gable roof. Main barn is frame with metal roof. Additions are frame and concrete block. Construction - 20th century bay.

Unknown (use): 2 story, one bay square, gable roof. Main section with flanking one-story, one-bay gable-roofed wings. Frame - weatherboarding, metal and wood shingle roofs. Construction - stud; set on brick piers.

Machine shed (2 of these) Long one-story with shed roof. Material - wide vertical boarding, sheet metal roof. Construction - Bay framed. Small trees set in ground used as posts.

Storage barn/with side shed pen: 1½ story with loft, gable roofed; 1 story shed pen. Material - wide vertical boarding and metal roof. Bay framed.


- 2. Site Description The house is reached by a lane immediately to the east which forms a circle in front of the kitchen and then continues on to the barns and fields behind. The several remaining outbuildings are arranged roughly in two rows parallel to and behind the house. In front of the house is a flat grassy lawn with large shade trees.
- 3. Views to/from site Bond Chapel is clearly visible across the road. In front of the house is woods. To the east are visible small houses (modern); to the east, north and west are cultivated fields with woods lines about $\frac{1}{2}$ -1 mile distant.


Use of Building

- 1. Current Tenant House since 1893
- 2. Historic Residence

History of Building/Past Ownership

The York Farm was a part of the estate of Col. E. Wilkens who died about 1880. An equity proceeding followed with his heirs seeking to divide his property. On February 12, 1883 (SB4/76) a deed for the 348 acre farm was awarded to Samuel M. Wilkens, an heir. At the time of Col. Wilkens ownership, there was another house on the property. Clearly shown on the 1877 Atlas, it was located at the end of a long lane, probably the farm lane that runs east of the present house. Presumably this Victorian house and some of the barns were constructed by Samuel Wilkens because it was standing when he sold the farm to Thomas W. Eliason, grandfather of the current owner, on October 7, 1893. The sale price, about \$2100.00 is very low for the farm and buildings. The true story is not known but legend holds that this was the cost of the house, an amount owed to Mr. Eliason, a lumber yard owner in Chestertown. (See K-49)









K-459 York Farm Rt. 289, Quaker Neck, near Chestertown M. Q. Fallaw - 3/29/86 View to west

K-459-25



K-459 York Farm Rt. 289, Quaker Neck, near Chestertown M. Q. Fallaw - 3/29/86 View to southeast

K-455-20